Weathertzanton Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW4064/1

Work Order Type: Weatherization

Audit Name: Audit-12012NW4064

CLIENT INFORMATION

Client Name: 12012NW4064 Address:

Client ID: 12012NW4064 , 38251

Alt. Client ID: Henry

CLIENT CONTACT INFORMATION

12012NW4064 Applicant/Person of
✓

Record

AGENCY INFORMATION

Agency: Northwest TN EDC Agency Phone: (731) 364-3228

Address: 231 S. Wilson Street Fax:

Dresden, TN 38225 *Email Address:*

Agency Contact: Radford, Randy Work Phone: (615) 686-3245

Cell Phone: (615) 335-7428

Email Address: Randy@energyhoundz.com

Company Name & License Number:	
Contractor's Signature	

COMMENT

Contractor to follow the Southeast Field Guide as applicable.

Client Name: 12012NW4064 Client ID: 12012NW4064 Alt. Client ID: Henry Work Order (Bid Form)
Work Order Name: WO/12012NW4064/1

Report Run On: 5/24/2010

DOE Weatherization Assistant Version 8.6.0 Page 1 of 13

Measures

Measure 1 Drywall Ceiling of Finished, Conditioned Attic (approx. 2	11 sq. ft		Component	s		ı	nspected
Comment Tape, float, and paint white							
• • • •			Estimated			Actual	
# Material / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor		1					
2 Miscellaneous Su		1					
Other Detail							
		Measur	e Sub Total:]	Sub Total:	
Field Notes:							
Measure 2 Replace Door Between Finis Conditioned Attic to Uncond Comment approx. 32 x 73 Existing door does not fit opening			Component Estimated	śs		Actual	nspected
# Material / Labor Description / Comment	Units	O41	Unit Cost	Total	Otv	Unit Cost	Total
# Material / Labor Description / Comment 1 Labor	Onits	Q ty 1	Omit Cost	Total	Qty		Total
2 Doors		1					
Other Detail							
Other Detail							
Other Detail							
Other Detail		Measur	e Sub Total:			Sub Total:	
Other Detail Field Notes:		Measur	e Sub Total:			Sub Total:	

Page 2 of 13

Report Run On: 5/24/2010

Measur	e 3 Infi	Itration Redctn			Componen	ts			Inspected
Commer	t -Air sea	al around all windows							
	-Air sea	al trim around all doors							
	-Air sea	al plumbing penetrations b	ehind was	sher ar	nd dryer and	under kit	chen		
	sink								
	-Air sea	al around breaker box in ba	athroom						
	-Air sea	al electrical penetrations al	oove brea	ker bo	x in bathroo	m			
	-Air sea	al door jam between bathro	oom and l	kitchen	l				
	-Air sea	al dryer vent penetration							
	-Air sea	al gap behind kitchen coun	tertop ba	ckspla	sh				
	-Air sea	al light fixture in living room	1						
	-Air sea	al all separations and gaps	in stairw	ell to fi	nished attic	(approx. 3	30 linea	ar	
	ft)								
	-Air sea	al door to unconditioned at	tic						
	-Clear	caulk base of panelling in o	conditione	ed attic					
					Estimated	<u> </u>		Actual	
# Materia	/ Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total

# Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total Labor 10 Miscellaneous Su Infiltration Reduction Each 1 Other Detail	
10 Miscellaneous Su Infiltration Reduction Each 1	otal
	-
Other Detail	
Other Detail	
Measure Sub Total: Sub Total:	
Field Notes:	

Client Name: 12012NW4064 Client ID: 12012NW4064 Alt. Client ID: Henry Work Order (Bid Form)
Work Order Name: WO/12012NW4064/1

Report Run On: 5/24/2010

DOE Weatherization Assistant Version 8.6.0 Page 3 of 13

C	Measure 4 DWH	Pipe Insulation			Componen	ts		ı	Inspecte
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
3	Other	DHW Pipe Insulation	Each	1					
C	Other Detail						1		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 5 DWH comment	I Tank Insulation			Componen	ts			Inspecte
#	Material / Labor				Estimated	,		Actual	
		Description / Comment	Units	- Otv	Estimated	·	Ofv	Actual	Total
	Hot water Equipm	Description / Comment DHW Tank Insulation	<i>Units</i> Each	Qty 1	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1	Labor					·	Qty		Total
1		DHW Tank Insulation	Each	1		·	Qty		Total
1 2 3	Labor	DHW Tank Insulation DHW Tank Insulation	Each Each	1		·	Qty		Total
1 2 3	Labor Other	DHW Tank Insulation DHW Tank Insulation	Each Each	1		·	Qty		Total
1 2 3	Labor Other	DHW Tank Insulation DHW Tank Insulation	Each Each	1		·	Qty		Total
1 2 3	Labor Other	DHW Tank Insulation DHW Tank Insulation	Each Each	1 1 1		·			Total
1 2 3	Labor Other	DHW Tank Insulation DHW Tank Insulation	Each Each	1 1 1	Unit Cost	·		Unit Cost	Total

Measure 6 Wa Comment	III Insulation			Componen				Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor								
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	206.2					
Other Detail								
			Measure	e Sub Total:		;	Sub Total:	
Measure 7 Wa	III Insulation		(Componen				Inspected
Comment				Estimated			Actual	
Comment # Material / Labor	Ill Insulation Description / Comment	Units	Qty	-		Qty		Inspected Total
Comment		Units		Estimated		Qty	Actual	
Comment # Material / Labor Labor		<i>Units</i> SqFt		Estimated		Qty	Actual	
Comment # Material / Labor Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated		Qty	Actual	
# Material / Labor Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated		Qty	Actual	
# Material / Labor Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated		Qty	Actual	
# Material / Labor Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty 190.6	Estimated			Actual	
# Material / Labor Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty 190.6	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor Labor 1 Insulation Other Detail	Description / Comment Wall Insulation - Blown		Qty 190.6	Estimated Unit Cost			Actual Unit Cost	

Measure 8 Wa	Ill Insulation			Componen	ts WL6			Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor								
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	73					
Other Detail			1					
			Measur	e Sub Total:			Sub Total:	
Measure 9 Wa	Ill Insulation			Component	ts WL3			Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor								
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	35					
Other Detail								
Field Notes:			Measur	e Sub Total:			Sub Total:	
Ticia Notes.			Measur	e Sub Total:			Sub Total:	
ricia Notes.			Measur	e Sub Total:		•	Sub Total:	

Me	easure 10 Wa	II Insulation			Componen	ts WL1			Inspected
Coi	mment								
					Estimated	<u> </u>		Actual	
# N	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
L	_abor								
1 I ı	nsulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	54					
Oth	ner Detail								
				Measur	e Sub Total:			Sub Total:	
Me	easure 11 Fill	Ceiling Cavity			Componen	ts A1			Inspected
		Ceiling Cavity hed attic on the side of the	e finished		•				Inspected
Coi			e finished <i>Unit</i> s		Componen Estimated Unit Cost		Qty	Actual Unit Cost	Inspected Total
Coi # N	<i>mment</i> Unfinis	hed attic on the side of the		attics	Estimated	<u> </u>	Qty	Actual	
<i>Coi</i> # <i>N</i>	mment Unfinis <i>flaterial / Labo</i> r	hed attic on the side of the		attics	Estimated	<u> </u>	Qty	Actual	
# N L	mment Unfinis //aterial / Labor _abor	hed attic on the side of the Description / Comment Attic Insulation - Blown	Units	attics Qty	Estimated	<u> </u>	Qty	Actual	
# N L	mment Unfinis Material / Labor Labor nsulation	hed attic on the side of the Description / Comment Attic Insulation - Blown	Units	attics Qty	Estimated	<u> </u>	Qty	Actual	
# N L	mment Unfinis Material / Labor Labor nsulation	hed attic on the side of the Description / Comment Attic Insulation - Blown	Units	attics Qty	Estimated	<u> </u>	Qty	Actual	
# N L	mment Unfinis Material / Labor Labor nsulation	hed attic on the side of the Description / Comment Attic Insulation - Blown	Units	Attics Qty 679	Estimated	<u> </u>		Actual	
# M L 1 III	mment Unfinis Material / Labor Labor nsulation	hed attic on the side of the Description / Comment Attic Insulation - Blown	Units	Attics Qty 679	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# M L 1 III	mment Unfinis Material / Labor Labor Insulation Mer Detail	hed attic on the side of the Description / Comment Attic Insulation - Blown	Units	Attics Qty 679	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 12	Wall Insulation			Componen	ts WL7			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Lab	oor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor								
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	73					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 13	Wall Insulation			Componen	<i>t</i> s WL10			Inspected
Measure 13 Comment	Wall Insulation			-				Inspected
Comment				Estimated	1		Actual	
Comment # Material / Lab		Units	Qty	-		Qty		Inspected Total
Comment		Units		Estimated	1	Qty	Actual	
Comment # Material / Lab		<i>Units</i> SqFt		Estimated	1	Qty	Actual	
Comment # Material / Lab Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated	1	Qty	Actual	
# Material / Lab Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated	1	Qty	Actual	
# Material / Lab Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated	1	Qty	Actual	
Comment # Material / Lab Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty 20	Estimated	1		Actual	Inspected
Comment # Material / Lab Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty 20	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Lab Labor 1 Insulation Other Detail	Description / Comment Wall Insulation - Blown		Qty 20	Estimated Unit Cost	1		Actual Unit Cost	

	ll Insulation			Componen	ts WL5			Inspecte
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor								
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	20					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Measure 15 Wal Comment	ll Insulation			Componen	ts WL2			Inspecte
	II Insulation			Componen Estimated			Actual	Inspecte
Comment # Material / Labor	Il Insulation Description / Comment	Units	Qty	-		Qty		Inspecte Total
Comment		Units		Estimated	1	Qty	Actual	
Comment # Material / Labor Labor		<i>Units</i> SqFt		Estimated	1	Qty	Actual	
Comment # Material / Labor Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated	1	Qty	Actual	
# Material / Labor Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated	1	Qty	Actual	
# Material / Labor Labor Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated	1	Qty	Actual	
# Material / Labor Labor Insulation	Description / Comment Wall Insulation - Blown		Qty 70.64	Estimated	1		Actual	

Commont	I Insulation			Componen	ts WL8			Inspecte
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor								
I Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	73					
Other Detail			1]		
			Measur	e Sub Total:		,	Sub Total:	
Measure 17 Wal	Linguistion							
Comment	insulation			Componen	ts WL9			Inspecte
Comment	i insulation			Component Estimated			Actual	Inspecte
	Description / Comment	Units	Qty	-		Qty		Inspecte Total
		Units		Estimated		Qty	Actual	
# <i>Material / Labor</i> Labor		<i>Units</i> SqFt		Estimated		Qty	Actual	
# <i>Material / Labor</i> Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated		Qty	Actual	
# Material / Labor Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated		Qty	Actual	
# Material / Labor Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated		Qty	Actual	
1 Insulation	Description / Comment Wall Insulation - Blown		Qty 122.6	Estimated			Actual	

	lean Blower and Coils (Ev nd Condenser)	/aporator		Component	ts		1	Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor			1					
2 Heating Equipm	nen		1					
Other Detail								
] []	Sub Total:	
			Measur	e Sub Total:		•	Sub Total:	
	O Monitor is Needed			Componen				Inspected
Comment				Estimated			Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected Total
Comment # Material / Labor	Description / Comment	Units Each		Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safe	Description / Comment		Qty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safe	Description / Comment ety CO monitor	Each	Qty 1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safe 2 Labor	Description / Comment ety CO monitor	Each	Qty 1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safe 2 Labor	Description / Comment ety CO monitor	Each Hour	Qty 1 1	Estimated			Actual	
Comment# Material / Labor1 Health and Safe2 Labor	Description / Comment ety CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Health and Safe 2 Labor Other Detail	Description / Comment ety CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Measure 20 Install Bathroom Exhaust Fan (out through wall)			Components				Inspected		
Comment									
			Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Health and Safe	ty Bathroom exhaust fan	Each	1						
2 Labor	Labor	Hour	1						
Other Detail									
				e Sub Total:		Sub Total:			
	stall Kitchen Exhaust Far ough wall)	n (out		Componen Estimated			Actual	Inspected	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Health and Safe	ty Kitchen exhaust fan	Each	1						
2 Labor	Labor	Hour	1						
Other Detail									
			Measure Sub Total:				Sub Total:		
Field Notes:									

Measure 22 Replace Return Filter			Components					Inspected	
Comment Include	Extra Filters								
		Estimated			Actual				
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Labor			1						
2 Heating Equipme	n		1						
Other Detail									
M			Measur	e Sub Total:		Sub Total:			
Measure 23 Smoke Detector is Needed Comment				Componen	ts	Inspected			
			Estimated			Actual			
							Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
		<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty		Total	
1 Health and Safety				Unit Cost	Total	Qty		Total	
1 Health and Safety	y Smoke detector	Each	1	Unit Cost	Total	Qty		Total	
# Material / Labor 1 Health and Safety 2 Labor Other Detail	y Smoke detector	Each	1	Unit Cost	Total	Qty		Total	
1 Health and Safety2 Labor	y Smoke detector	Each	1	Unit Cost	Total	Qty		Total	
1 Health and Safety2 Labor	y Smoke detector	Each Hour	1	Unit Cost	Total			Total	
1 Health and Safety2 Labor	y Smoke detector	Each Hour	1		Total		Unit Cost	Total	